

COON CREEK WATERSHED DISTRICT

Request for Board Action

MEETING DATE: June 9, 2025
AGENDA NUMBER: 15
ITEM: Water Management Asset Condition Assessment

POLICY IMPACT: Policy
FISCAL IMPACT: Budgeted

REQUEST

Receive inspection report

BACKGROUND

District-owned-and-maintained water control structures are inspected annually as part of the District's O&M program and the District insurance and NPDES requirements.

The average age of the structures is 33 years. Facility life is estimated to be 50 years based on the life expectancy of concrete.

ISSUES/CONCERNS

The 2023 inspection found the following:

Facility	City	Purpose of Facility	Year Built	Age (yrs)	Condition
Lake Andover Outlet	Andover	Lake elevation	1995	30	Good
Crooked Lake Outlet/Dam	Coon Rapids	Lake elevation	2016/1959	9/66	Good/Good
Laddie Lake Outlet	Blaine	Lake elevation	2020	5	Good
Lake Netta Outlet	Ham Lake	Lake elevation	1978	47	Good
Ham Lake Outlet	Ham Lake	Lake elevation	1965	60	Good
D 58 Timberline Weir	Ham Lake	Approved ditch elevation	2003	22	Good
D 58 Prairie Creek Weir	Ham Lake	Approved ditch elevation	2003	22	Good
D 58-7-2 Pinger's Plaza	Ham Lake	Approved ditch elevation	1991	34	Good
D 58-6 Structure	Ham Lake	Approved ditch elevation	1989	36	Good
D 58-7 Structure	Andover	Approved ditch elevation	1989	36	Good

RECOMMENDATION

1. Receive inspection report
2. Re-Inspect in 2026



